PERIPHERALS

<For holder bores> Cleaning tool


- α WIPER CLEANER (for chuck bore: ø3 ø12)
- Developed for cleaning the clamping bores such as hydraulic chucks and shrink fit holders.

Inner diamet ø3 and up

Use a cleaner matching the chuck bore size.

AWC5 - 6

8 EII



Cleaning strips

Cleaning strips

AWC3 - 4

AWC7 - 12

ð


Cleaning strips

Ideal for small-diameter bores! Insert and extract the cleaner to remove inner chips, particles and oil.

Model	øD	L	
AWC 3	3	7	
AWC 4	4		
AWC 5	5	20	
AWC 6	6		
AWC 7	7		
AWC 8	8		
AWC 9	9	26	
AWC10	10		
AWC11	11	31	
AWC12	12		

1. øD in table = supported holder bore ød

- TK CLEANER (For chuck bores: ø13 ø42)
- Wipes off particles and oil in chuck bore and keeps your machining safe and secure.



√ل


When the lever is released, spring action automatically causes the

cleaning strips to contact the bore.

For MEGA DOUBLE POWER CHUCK/ NEW HI-POWER MILLING CHUCK/HYDRAULIC CHUCK

Model	Supported holder bore (Ø)	L	Lı	Number of cleaning strips
TKC13	13		106	2
TC14	14	60		
TKC 15	15			
16	16			
18	18	70		
20	20			
25	25	80		3
32	32	100		
40	40	105	121	4
42	42	105		

* Select in accordance with the chuck bore



IN

᠕

into the holder bore.

When the lever is pressed out, the upper part slides and the diameter is reduced, allowing it to fit smoothly

